


## Existing condition of the substructure (abutment)

**Ranges from poor to fair**



**Girder**

These pictures show the deterioration of the east abutment.

Note the deterioration of the abutment under the girder in the right photo above.



The left photo above shows a section of concrete that has failed and is being held in place by the utility pipe. The right photo shows a failure that has occurred in the back wall of the east abutment.